



Laboratory: Plot No. 82A, Sector - 5, IMT Manesar, Gurugram - 122052, Haryana
 Branch Off: Plot No. 24 & 25, Narayan Vihar, B-Block, Jaipur - 302035, Rajasthan
NABL Accredited | MoEF&CC Recognized | ISO 9001|ISO 14001|ISO 45001

Test Report

Sample Number :	VEL/WW/1912240001	Report No. :	VEL/WW/1912240001
Name & Address of the Party :	M/s Maharani Innovative Paints Pvt. Ltd. 49th Km Stone, Khasra No. 122, Mathura Road, Village - Prithla, Dist - Palwal, Haryana Haryana	Format No :	7.8 F-01
		Party Reference No :	Nil
		Reporting Date :	28/12/2019
		Period of Analysis :	24/12/2019-28/12/2019
Sample Description :	Waste Water	Receipt Date :	24/12/2019
Location :	ETP Inlet(ETP Plant)	Sampling Date :	24/12/2019
Sample Collected by :	VEL Representative (Mr. Mukesh)	Sampling Quantity :	2.0 Ltr.
Preservation :	Refrigerator	Sampling Type :	--
Sampling and Analysis Protocol :	APHA & IS		

S.No.	Test Parameters	Test Method	Result	Unit
1	pH	APHA 4500 H+B Electrometric Method:2017	8.38	--
2	Total Suspended Solids	APHA 2540 D Gravimetric Method	210.00	mg/l
3	Oil & Grease	APHA 5520 B Partition Gravimetric Method:2017	10.80	mg/l
4	BOD (3 days @ 27°C)	APHA 5210 C Ultimate BOD Test:2017	86.00	mg/l
5	COD	APHA 5220 B Open Reflux Method:2017	384.40	mg/l

End of Report

Mamata Nayak

(Signature)

Gaurav Chauhan

(Signature)
 (Approved By)
 Quality Manager

NOTE: a) The results listed refer only to the tested samples & applicable parameters
 b) Total liabilities of our lab will be restricted to the invoice amount only
 c) The sample will be destroyed after retention time unless otherwise specified
 d) This report is not to be reproduced wholly or in part and cannot be used as evidence in the court of law



Vardan EnviroLab



Laboratory: Plot No. 82A, Sector - 5, IMT Manesar, Gurugram - 122052, Haryana
Branch Off: Plot No. 24 & 25, Narayan Vihar, B-Block, Jaipur - 302035, Rajasthan
NABL Accredited | MoEF&CC Recognized | ISO 9001|ISO 14001|ISO 45001

Test Report

Sample Number : VEL/WW/1912240002

Name & Address of the Party : M/s Maharani Innovative Paints Pvt. Ltd.
49th Km Stone, Khasra No. 122, Mathura Road, Village
- Prithla, Dist - Palwal, Haryana Haryana

Report No. : VEL/WW/1912240002

Format No : 7.8 F-01

Party Reference No : Nil

Reporting Date : 28/12/2019

Period of Analysis : 24/12/2019-28/12/2019

Receipt Date : 24/12/2019

Sampling Date : 24/12/2019

Sampling Quantity : 2.0 Ltr.

Sampling Type : --

Sample Description : Waste Water
Location : ETP Outlet(ETP Plant)
Sample Collected by : VEL Representative (Mr. Mukesh)
Preservation : Refrigerator
Parameter Required : As per work order
Analysis Protocol : APHA & IS

S.No.	Test Parameters	Test Method	Result	Unit	Limits as Per EPA (Sche.-VI)		
					Inland Surface Water	Public Sewers	Land for Irrigation
1	pH	APHA 4500 H+B Electrometric Method:2017	6.87	--	5.5 - 9.0	5.5 - 9.0	5.5 - 9.0
2	Total Suspended Solids	APHA 2540 D Gravimetric Method	68.00	mg/l	100.0	600.0	200.0
3	Oil & Grease	APHA 5520 B Partition Gravimetric Method:2017	3.20	mg/l	10.0	20.0	10.0
4	BOD (3 days @ 27°C)	APHA 5210 C Ultimate BOD Test:2017	21.00	mg/l	30.0	350.0	100.0
5	COD	APHA 5220 B Open Reflux Method:2017	119.40	mg/l	250.0	--	--

End of Report

Mamata Nayak

(Signed By)

Gaurav Chauhan

(Approved By)
Quality Manager

NOTE: a) The results listed refer only to the tested samples & applicable parameters
b) Total liabilities of our lab will be restricted to the invoice amount only
c) The sample will be destroyed after retention time unless otherwise specified
d) This report is not to be reproduced wholly or in part and cannot be used as evidence in the court of law

Page No, 1/1

www.vardan.co.in

Tel: 0124-4343750, 4343752, 4343753 | E-mail: lab@vardanenviro.net, bd@vardanenviro.net



Vardan EnviroLab



Laboratory: Plot No. 82A, Sector - 5, IMT Manesar, Gurugram - 122052, Haryana
Branch Off: Plot No. 24 & 25, Narayan Vihar, B-Block, Jaipur - 302035, Rajasthan
NABL Accredited | MoEF&CC Recognized | ISO 9001 | ISO 14001 | ISO 45001

Test Report

Sample Number : VEL/WW/1912240003

Name & Address of the Party : M/s Maharani Innovative Paints Pvt. Ltd.
49th Km Stone, Khasra No. 122, Mathura Road, Village
- Prithla, Dist - Palwal, Haryana Haryana

Report No. : VEL/WW/1912240003

Format No : 7.8 F-01

Party Reference No : Nil

Reporting Date : 28/12/2019

Period of Analysis : 24/12/2019-28/12/2019

Receipt Date : 24/12/2019

Sampling Date : 24/12/2019

Sampling Quantity : 2.0 Ltr.

Sampling Type : --

Sample Description : Waste Water
Location : STP Outlet(STP Plant)
Sample Collected by : VEL Representative (Mr. Mukesh)
Preservation : Refrigerator
Parameter Required : As per work order
Analysis Protocol : APHA & IS

S.No.	Test Parameters	Test Method	Result	Unit	Limits as Per EPA (Sche.-VI)		
					Inland Surface Water	Public Sewers	Land for Irrigation
1	pH	APHA 4500 H+B Electrometric Method:2017	6.76	--	5.5 - 9.0	5.5 - 9.0	5.5 - 9.0
2	Total Suspended Solids	APHA 2540 D Gravimetric Method	34.00	mg/l	100.0	600.0	200.0
3	Oil & Grease	APHA 5520 B Partition Gravimetric Method:2017	2.10	mg/l	10.0	20.0	10.0
4	BOD (3 days @ 27°C)	APHA 5210 C Ultimate BOD Test:2017	23.00	mg/l	30.0	350.0	100.0
5	COD	APHA 5220 B Open Reflux Method:2017	84.60	mg/l	250.0	--	--

End of Report

Mamata Nayak

Gaurav Chauhan

Approved By
Quality Manager

NOTE: a) The results listed refer only to the tested samples & applicable parameters
b) Total liabilities of our lab will be restricted to the Invoice amount only
c) The sample will be destroyed after retention time unless otherwise specified
d) This report is not to be reproduced wholly or in part and cannot be used as evidence in the court of law

Page No. 1/1

www.vardan.co.in

Tel: 0124-4343750, 4343752, 4343753 | E-mail: lab@vardanenvironet.com, bd@vardanenvironet.com